



M-E Technical, LLP

Syncro Spark IV


Jan 2005




20 deg retard
from 6000 to 1500 RPM
[Bridge all three pads]



26 deg retard
from 4000 to 1475 RPM
[Default map]
No bridges



20 deg retard
from 4000 to 1475 RPM
[Bridge center pad
and inside pad]



26 deg retard
from 6000 to 1500 RPM
[Bridge center pad
and outside pad]

Inspect carefully for unintended bridges after cleaning rosin from board