

Version Information.

HPP-22 V1.04(1)

Fixed:

- Unable to Read Sensor Data in Czech, and Italian

Aurora 9 v1.07(2)

Fixed:

- Imperial Measurement Display Error Over 60MPH

HPP-22 V1.04(0)

New Features:

- OPTIMA 7/9 Fail-Safe setup function: Now you can adjust fail-safe function of Optima 7 & 9 receivers through HPP-22.
- 3D Google Earth view function: Use the HTS-SS flight data and play back your flight path on the 3D Google Earth back ground.
- OPTIC 6 SPORT 2.4 Setup: Now you can adjust setup of Optic 6S 2.4 through HPP-22.

Added Features:

- AURORA 9 Multi-Language Menu Available in Spanish: Spanish version Aurora 9 Menu is now available
- Aurora 9 V1.07(1) upgrade version can be selected on the menu with HPP-22 V1.04(0) upgrade.

Fix:

- OPTIC 6 SPORT V1.04(1) & OPTIC 6 SPORT 2.4 V1.01(1)
When ADIF function activated, and Crow mix is in use, CH 5 did not respond, when SW 1 has selected as STCK function.

HPP-22 V1.03

- AURORA 9 Multi-Language Menu Available in English, German, French, Italian, and Czech

HPP-22 V1.02

- Aurora 9 v1.07 Upgrade Information.

Added Functions:

- System Password Lock Function: You can't have system access without correct password.
- Quick Model Select Function: You can confirm & select your model from the start up screen.
- Receiver Battery Low Voltage Warning Function: You can select the Low Battery Warning Alarm activation level.
- Touch Beep Sound On/Off Function: You can turn on and off touch screen button sound.
- Touch Screen Calibration Function: Now you can do touch screen calibration for your Aurora 9.
- Warning Selection at Start up Function: Now you can choose to turn on or off for two conditions of startup warnings
(Abnormal Throttle and Flight Condition)

Modified Functions (improved):

- Timer Reset Method: Press & hold the Timer (1 or 2) screen for about 2 seconds which you want to reset.

Etc.:

- Menu Name Changed: Power > SYS. MGMT, Auto Power Off > Auto Hibernation.

- SPECTRA 2.4 v2.00 Upgrade Information.

Low Battery Warning Function
HTS-SS 2D display

- OPTIMA 7/9 v2.00 Upgrade Information.

HPP-22 V1.01

- Transferred server and changed download site information